


## Bias-Ply Repair Chart



<b>C</b>		<b>PR</b> PLY RATING	-6	8 - 10	12 - 14	16 - 18
max. mm	max. inch					
25	1"	PN-Nr.	20	20	20	20
50	2"	PN-Nr.	20	20	21	23
75	3"	PN-Nr.	20	23	23	24
125	5"	PN-Nr.	21	24	24	25
175	7"	PN-Nr.	22	25	25	-



<b>C</b>		<b>PR</b> PLY RATING	-8	10 - 12	14 - 16	18 - 20	22 - 24
max. mm	max. inch						
25	1"	PN-Nr.	40	41	41	42	42
50	2"	PN-Nr.	40	41	42	42	-
75	3"	PN-Nr.	-	42	42	-	-



<b>C</b>		<b>PR</b> PLY RATING	-4	6 - 8	10 - 12	14 - 16	18 - 20	22 - 24	-12	14 - 18	20 - 24
max. mm	max. inch										
10	3/8"	PN-Nr.	2	2	3	3	4	4	2	3	3
15	1/2"	PN-Nr.	3	3	4	4	5	5	2	3	4
25	1"	PN-Nr.	3	4	5	6	6	6	3	4	5
35	13/8"	PN-Nr.	4	4	5	6	7	7	3	4	5
50	2"	PN-Nr.	5	5	6	7	8	8	5	5	6
75	3"	PN-Nr.	-	-	7	7	9	9	6	6	7
100	4"	PN-Nr.	-	-	8	8	9	10	7	7	8
125	5"	PN-Nr.	-	-	-	10	10	-	-	8	8



PN o2 - o10



PN o5 S - o10 S  
S = Sidewall

